ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
10

Ward Name
Dodda Bommasandra

Street ID
W0006, W0003, W0107, W0014, W0092, W0119, W0004, W

Street Name
NA, Subhash Chandra Bose Lyt, 2nd Crs, S Krishnappa Lyt, 1st Crs

Significant Landmark
Doddabommasandra Chomundeshwari layout

Segment No.
10/C-W0006/S031736

Total Length (m)
75.50

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	9.02	77.553335	13.062272	77.553416	13.062252	W0134	W0134
2	6.68	77.554062	13.058945	77.554069	13.059005	W0345	W0345
3	6.44	77.555907	13.060058	77.555966	13.060052	W0276	W0276
4	9.46	77.556375	13.065907	77.556403	13.065988	W0107	W0107
5	8.14	77.557353	13.065622	77.557378	13.065691	W0119	W0119
6	6.77	77.557794	13.066836	77.557817	13.066893	W0117	W0117
7	9.51	77.557309	13.068437	77.557394	13.068415	W0014	W0014
8	7.41	77.558138	13.070147	77.558200	13.070121	W0004	W0004
9	12.07	77.556157	13.070590	77.556206	13.070688	W0003	W0003

Work Details

History of Road / Lane / Circles

Name of the Work
Construction of Culverts at Ramachandrapura Doddabommasandra Chomundeshwari layout and Nanjjiappa layout in ward no 10 Doddabommasandra Vidyaranayapur

Sanctioned Estimated Amount (Rs.)
1000000

Sanctioned Year
2014

Year
2014 - 2015

Type of Work
Others

Other Work Type
Culverts

Tender
Tender

Work Details
Construction of Culverts at Ramachandrapura Doddabommasandra Chomundeshwari layout and Nanjjiappa layout in ward no 10 Doddabommasandra Vidyaranayapura Sub-Division Yelahanka zone

Job No. / Work Code
010-15-000047

Work Order No.

Work Order Date

Period of Extention

EE/BTP/ BBMP/E-PMT/WO/313/2014-15	16/02/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
17/11/2015	16/11/2016	Yes

Contractor Details

Name of Contractor	**Contractor Reg No (BBMP/PWD)**	**Expenditure Booked \ Released (Rs)**
B S THYAGARAJ		0.00
Phone No.	**E-Mail ID**	
9886368484		

Field Inspection Details

Number of Trees	**Any Other Information**	**Name**
6		MADHAVA RAO
Date of Inspection	**Remarks**	
28/01/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone:	YELAHANKA	**Ward No:**	10	**Ward Name:**	Dodda Bommasandra	**Street ID:**	W0006, W0003, W0107, W0014,

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	28/01/2017	27/02/2017	COMPLETED
SE	VASU K M	28/01/2017	27/02/2017	COMPLETED
EE	MOHAN DAS HT	28/01/2017	27/02/2017	COMPLETED
AEE	SHIVAKUMAR	28/01/2017	27/02/2017	COMPLETED
AE	MADHAV RAO	28/01/2017	27/02/2017	COMPLETED
AE	MADHAV RAO	28/01/2017	27/02/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0006, W0003, W0107, W0014,